Proposed Changes to Plainwell #2 Dam Area Post-TCRA Monitoring for 2013

| Prior Approach | Proposed Approach for 2013 | Rationale |
|--|----------------------------------|---|
| Tree and Shrub Survival Monitoring | | |
| Tree and shrub count | Continue same | Document if survivability metric is met. |
| Bank Stability | | |
| Visual observation and photo-documentation | Modify | Collect land-based and water-based photos to supplement discontinuation of BEHI and instrument survey |
| BEHI rating | Discontinue | Perform after site walk if areas of erosion are observed and it is decided that quantitative erosion potential data is needed in those specific locations (both BEHI and survey) |
| Instrument survey at 14 locations with highest potential for erosion | Discontinue | |
| Floodplain Vegetation Monitoring | | |
| Herbaceous vegetation monitoring | Modify | Achieved ground cover metric in 2011 (99%) and 2012 (99.5%). Remove detailed quadrant count. Perform qualitative visual observation and photo documentation in conjunction with tree and shrub count. |
| Invasive Species Assessment | Continue same | Invasive species were identified in 2011 and 2012. |